

Fig 3

[illegible]

NOTE:
1. FORCE RETAINING BRACKET IN DIRECTION SHOWN WHILE TIGHTING FLAT HEAD SCREW TO IMPROVE HOLE ALIGNMENT FOR MOUNT COVER ASSEMBLY.

[illegible]

NOTES:

1. MATERIAL: 4130
2. ZINC-PHOSPHATE COAT PER P-00201
3. THE FLANKS OF THE THREADS REQUIRE A 63 FINISH




Fig 3B

SECTION A-A

3A

[illegible]

FOUO-892450






FIG. 4

Fig 5A



5
4

[illegible]



SECTION A-A

FIG 6B




FIG 6A




FIG 6